

**CITY OF BALTIMORE WET WEATHER CONSENT DECREE  
SMOKE AND DYED WATER TESTING FORM**

Page 1 of 5

Sewershed: Low Level  
Subsewershed: 42

Company: REI/DRAYCO

Date: 09/11/2008

Test Type: Smoke

Ground Condition:  
Dry: ☒ Damp: ☐ Wet: ☐


Supervisor: E.R. Crew: 04

Manhole ID: S21W\_021MH

Test ID: 1029-546

Notifications Made: ☒ X  
Residents, Fire, 311

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



[illegible]

**CITY OF BALTIMORE**  
**SMOKE TESTING OBSERVATION SUMMARY**  
**LOW LEVEL SEWERSHED**  
BALTIMORE CITY PROJECT 1029  
REI/DRAYCO

Unique Test ID: 546	Date: 09/11/2008	Basin: LL - 42	Manhole ID: S21W__021MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: S19W__024MH			
Source Type: 01 Main Sewer		Location: 11 Field/Woods	
Sector: 01 Public		Severity: 03 Moderate	Drainage Area: 0
Comments: THIS IS ABANDONED MANHOLE S19W__024MH AND IT SMOKED WHEN BLOWING FROM S21W__021MH.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01  
Filename: 1029-546\_OB01-01.jpg



**CITY OF BALTIMORE**  
**SMOKE TESTING OBSERVATION SUMMARY**  
**LOW LEVEL SEWERSHED**  
BALTIMORE CITY PROJECT 1029  
REI/DRAYCO

Unique Test ID: 546	Date: 09/11/2008	Basin: LL - 42	Manhole ID: S21W__021MH
Defect No: OB02	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: 2356 WASHINGTON BLVD.			
Source Type: 02 Service Line		Location: 11 Field/Woods	
Sector: 02 Private		Severity: 03 Moderate	Drainage Area: 1
Comments: SMOKE COMING FROM GROUND IN FIELD.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01  
Filename: 1029-546\_OB02-01.jpg

**CITY OF BALTIMORE**  
**SMOKE TESTING OBSERVATION SUMMARY**  
**LOW LEVEL SEWERSHED**  
BALTIMORE CITY PROJECT 1029  
REI/DRAYCO

Unique Test ID: 546	Date: 09/11/2008	Basin: LL - 42	Manhole ID: S21W__021MH
Defect No: OB03	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: S19W__020MH			

Source Type: 01 Main Sewer

Location: 02 Asphalt


Sector: 01 Public

Severity: 03 Moderate

Drainage Area: 0

Comments: SMOKE COMING FROM S19W\_\_015MH WHICH MUST BE CONNECTED TO S19W\_\_020MH  
ALTHOUGH NO CONNECTION IS SHOWN ON MAP. CANNOT LOCATE S19W\_\_021MH. THE MANHOLES  
HERE ARE FOR WATER VALVES.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB03-01  
Filename: 1029-546\_OB03-01.jpg